
## Wiring Diagram for I Ph. DOL Starting





Contactor with Thermal Overload unit attached